# CQS1000 Product Revisions

Released: *May 2, 2019*
Firmware: **CQS54080V3-1.0.3**   Software: **CQSView 2.0.0.0**
Framework: .NET 4.0   Windows: XP (sp3), Vista, W7, W8, W10
Updates: - Added Firing Pulse timeout
                  - Added Firing Pulse input setting
                  - Fixed Tiled view mode scaling problem
                  - Added Pass/Fail and Connection status to tile-view-mode curve images

Released: *June 23, 2016*
Firmware: **CQS54080V3-1.0.2**   Software: **CQSView 1.3.0.0**
Framework: .NET 4.0   Windows: XP (sp3), Vista, W7, W8, W10
Updates: - Updated connection status which was missing from previous releases.
                  - Various bug fixes and cosmetic changes.
                  - Added new curve image capture
                  - Updated AutoGen and Device Discovery UI

Released: *December 2, 2015*
Firmware: **CQS54080V3-1.0.0**   Software: **CQSView 1.2.3.1**
Framework: .NET 4.0   Windows: XP (sp3), Vista, W7, W8, W10
Updates: - Initial Release

NOTE:
OES is committed to supporting our customers by continuously improving our products with new features and enhancements to advance the product performance in the production environment. These new product versions are made available to our customers following extensive testing and validation to ensure reliable performance. Since we cannot replicate the production environment it is recommended that the customer validate the new version for performance specific to your machine, process, and production environment to ensure this new release meets performance expectation.

www.oestechnologies.com   Quality without Question

Product specifications and related information subject to change without notice.